HAZ SEKWIZZION REEN CINEN BY THE CLIENT TO YZZION CAZEN RWM AS THEIR HOME DEALER?? YES / NO PARTS-----QTY---FP-NUMBER-------DESCRIPTION-------UNIT PRICE-JOB # 7 TOTAL PARTS JOB # 7 TOTAL LABOR & PARTS J# 8+06BMZ *BRAKE SYSTEM TECH(S):1842 CUSTOMER STATES WHILE DRIVING, THE VEHICLE WILL PULL TO THE RIGHT. RETROFIT CONVERSION FOR PULL DRIFT COMPENSATION 1842 DC:3243021500 LO:WT-.5 FOR SWAPPING FRONT WHEELS AND TEST DRIVES, 00 00 006-.4, 61 21 528-.1 AND 61 00 730-.4 TEST DROVE VEHICLE, DUPLUCATED CUST COMPLAINT, WHEN DRIVING VEHICLE PULLS, CHECKED TIRE PRESSURES-TO SPEC, VEHICLE ALREADY ALIGNED LAST VISIT, SWAPPED FRON WHEELS, TEST DROVE, STILL SAME CONCERN, VEHICLE PRODUCTION DATE IS 3/16, HOOKED UP BMW APPORVED BATTERY CHARGER, RAN FAULTS, NO FAULTS IN SYSTEM RELATED TO COMPLAINT, PROGRAMMED VEHICLE AND RETROFIT PULL DRIFT COMPENSATION, TEST DROVE ON GOOD FLAT ROAD AND

ARTS-----QTY---FP-NUMBER-------DESCRIPTION------UNIT PRICE

VEHICLE DOES NOT PULL.

JOB # 8 TOTAL PART

JOB # 8 TOTAL LABOR & PAR