

Just BlauMitWeiss LLC

Service Estimate 19054

Name Address	Customer, Test blah	Company Address 2		Created Time Promised Advisor Division PO#	07/22/20 1:18 PM Justin JB 1 of 1	YEAR MAKE MODEL LIC FLEET BODY/CLR KEY TAG	2015 BMW M3
Home Work Fax		VIN DOM	P966713	Page#			

Job Description

Replace front coil springs with lowering springs	Line Total	1111.50
	Labor	1111.50
	Parts	0.00
	Sublets	0.00

Replace rear coil springs with lowering springs	Line Total	345.80
	Labor	345.80
	Parts	0.00
	Sublets	0.00

4-Wheel Alignment

Test drive and note any specific alignment symptoms.
 Inspect the suspension components, including the sub frame support bushings, for wear.
 Inspect tires and inflate accordingly.
 Measure ride height and correct as needed.
 Adjust rear camber as needed.
 Adjust rear toe as needed.
 Adjust front caster and camber as needed.
 Adjust front toe to thrust line.
 Check steering wheel for proper centering and correct as needed.
 Test drive to confirm original complaint is resolved, the steering wheel is centered and no pulling condition exists.

Line Total	200.00
Labor	200.00
Parts	0.00
Sublets	0.00

Just BlauMitWeiss
3251 Highland Ave. | Cincinnati OH 45213

(513) 271-5878 | Fax (513) 271-8509

YOU MUST INITIAL AN OPTION -AND- SIGN PRIOR TO ANY WORK BEING PERFORMED.
 In accordance with OHIO Law we are required to provide you with an estimate for repairs over \$25.00 (twenty-five dollars).

_____ I do not require an estimate _____ Oral Estimate _____ Written estimate

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for

Estimate Total	
Labor	\$1,657.30
Parts	\$0.00
Sublets	\$0.00
Supplies	\$34.73
Subtotal	\$1,692.03
Tax	\$118.44
Total	\$1,810.47